
















# Assembly Instruction

P1

## ASSEMBLY TIPS

1. Remove hardware from box and sort by size.
2. Please check to see that all hardware and parts are present prior start of assembly
3. Please follow attached instructions in the same sequence as numbered to assure fast & cas. assembly

<b>A</b>  X1	<b>B</b>  X1	<b>D</b>  X1	<b>E</b>  X1		
<b>F</b>  X1	<b>G</b>  X1	<b>H</b>  X3	<b>I</b>  X1	<b>J</b>  X3	
 X8	<b>L</b>  X9	<b>M</b>  X9	<b>N</b>  X9	<b>O</b>  X1	<b>P</b>  X32