



2510


ASSEMBLING INSTRUCTION



A x1pc



B x1pc



C x1pc



Dx4pcs



E x4pcs
M8x30



F x4pcs
M6*13



Gx4pcs
M6*16



H x4pcs
Ø6xØ16x1.0



I x1pc




Jx4pcs
M8




Kx1pc

step1.



step2.



step3.

